
Software Release Notes

Boxer version 1.7.0

This document provides the changes from Boxer version 1.6.1 to 1.7.0.

Affected products

The following products are affected.

- Boxer 4K models
- Boxer 2K models
- Boxer 30
- Mirage 304K

Purpose of release

The primary purpose of this release is to introduce the following features:

- Added Guardian support on Boxer 2K projector models.
- Improved Christie View port configurations and input selection.
- Provided minor fixes and improvements over version 1.6.1.

Notes

Note the following about upgrading to version 1.7.0:

- Upgrading a projector from USB requires the software package be located in the root of the USB flash drive. The drive must be formatted using a FAT-based file system.
- After updating from 1.3.2 or older versions to 1.7.0, a full AC reboot is required.
- This software does not allow for downgrading to software versions prior to 1.5.3.

Known issues

This release of Boxer contains the following known issues:

- In some cases when using single-link DVI signals, the unused secondary receivers disrupt the signal detection logic. This appears as occasional screen flashes while the projector attempts to re-synchronize to the incoming video.
Resolution: To disable the secondary receivers, issue the serial command (DDD 1) to the projector.
- The zoom controls for the lens are not enabled.

Workaround: Manually calibrate the lens by issuing the (LCB+ZOOM) serial command.

- Closing the web user interface while performing a keystone adjustment may result in the keystone corners still being displayed on screen.

Workaround: To remove the corners from the screen, open and close the Keystone menu.

- Certain low-resolution signals, including HDMI-3D frame-packed, may exhibit frame tearing if the frame delay value is set to the minimum.

Resolution: To eliminate tearing, increase the frame delay value.

- The liquid cooling flow sensor may report 0 L/min. This may invoke a pump-priming cycle but does not always indicate a low-flow condition. For more information, see the *Boxer Liquid Cooling Module Error Code Technical Bulletin (P/N: 020-200391-XX)*.
- Changing the network configuration from Static IP to DHCP, while the DHCP server is unavailable or the cable is unplugged, causes the software to become unresponsive for approximately 90 seconds.

Technical support

Technical support for Christie products is available at:

- North and South America: +1-800-221-8025 or Support.Americas@christiedigital.com
- Europe, Middle East, and Africa: +44 (0) 1189 778111 or Support.EMEA@christiedigital.com
- Asia Pacific: +65 6877-8737 or Support.APAC@christiedigital.com