
SOFTWARE RELEASE NOTES

LWU505 / LW555 / LX605 / LX505

Applies to the Following Products	Prepared For
<ul style="list-style-type: none">• LWU505• LW555• LX605• LX505	Public

Summary

The new firmware fixes the HDMI image freeze that occurs with HDMI signals connected to the projector through a switcher.

Firmware Files

- LWU505 (Chassis # 00) : KH2AL_V103_1013.exe, (Chassis # 01) : KH2AM_V203_1016.exe
- LW555 (Chassis # 00) : KK8AL_V104_1013.exe, (Chassis # 01) : KK8AM_V204_1014.exe
- LX605 (Chassis # 00) : KA8AL_V105_1021.exe, (Chassis # 01) : KA8AM_V204_1023.exe
- LX505 (Chassis # 00) : KZ5AL_V105_1021.exe, (Chassis # 01) : KZ5AM_V204_1023.exe

New Features and Enhancements

- The firmware ensures that when the output resolution on the video source/computer is changed, the frame reset will occur correctly and prevent the freeze.

Technical Support

North and South America: +1-800-221-8025 or tech-support@christiedigital.com

Europe, Middle East and Africa: +44 (0) 1189 778111 or techsupport-emea@christiedigital.com

Asia / Pacific: tech-asia@christiedigital.com