
INFORMATION BULLETIN

Firmware Update

Applies to the Following Products	Prepared For
<ul style="list-style-type: none">• LWU505• LW555• LX605• LX505	Public

A firmware update is available for the LWU505, LW555, LX605 and LX555 projectors to address potential HDMI image freezing that may occur when signals are connected through a switcher.

The available firmware update files listed below:

- LWU505 (Chassis # 00) : KH2AL_V103_1013.exe, (Chassis # 01) : KH2AM_V203_1016.exe
- LW555 (Chassis # 00) : KK8AL_V104_1013.exe, (Chassis # 01) : KK8AM_V204_1014.exe
- LX605 (Chassis # 00) : KA8AL_V105_1021.exe, (Chassis # 01) : KA8AM_V204_1023.exe
- LX505 (Chassis # 00) : KZ5AL_V105_1021.exe, (Chassis # 01) : KZ5AM_V204_1023.exe

Resolution

To prevent image freeze, this firmware version ensures correct activation of the frame reset when the output resolution on the video source is changed.

Technical Support

North and South America: +1-800-221-8025 or tech-support@christiedigital.com

Europe, Middle East and Africa: +44 (0) 1189 778111 or techsupport-emea@christiedigital.com

Asia / Pacific: tech-asia@christiedigital.com