

---

# Software Release Notes

---

## Christie Eclipse version 2.1.0

This document provides the changes from Christie Eclipse version 2.0.0 to Christie Eclipse 2.1.0.

### Affected products

The following products are affected:

- Christie Eclipse

### Purpose of release

The primary purpose of this release is to provide the following new features and updates:

- Added support for 3D.
- Removed the **Integrator Rod** internal test pattern.
- Enabled the Low AC input error.
- Removed the **LOAC** menu item from Service menu.
- Added support for the VOM-HBI.
- Increased the time for the interlock to open after power down from 5 to 60 seconds.

### Technical support

Technical support for Christie Enterprise products is available at:

- North and South America: +1-800-221-8025 or [Support.Americas@christiedigital.com](mailto:Support.Americas@christiedigital.com)
- Europe, Middle East, and Africa: +44 (0) 1189 778111 or [Support.EMEA@christiedigital.com](mailto:Support.EMEA@christiedigital.com)
- Asia Pacific ([support.apac@christiedigital.com](mailto:support.apac@christiedigital.com)):
  - Australia: +61 (0)7 3624 4888 or [tech-Australia@christiedigital.com](mailto:tech-Australia@christiedigital.com)
  - China: +86 10 6561 0240 or [tech-supportChina@christiedigital.com](mailto:tech-supportChina@christiedigital.com)
  - India: +91 (80) 6708 9999 or [tech-India@christiedigital.com](mailto:tech-India@christiedigital.com)
  - Japan: 81-3-3599-7481
  - Singapore: +65 6877-8737 or [tech-Singapore@christiedigital.com](mailto:tech-Singapore@christiedigital.com)
  - South Korea: +82 2 702 1601 or [tech-Korea@christiedigital.com](mailto:tech-Korea@christiedigital.com)
- Christie Professional Services: +1-800-550-3061 or [NOC@christiedigital.com](mailto:NOC@christiedigital.com)