
Software Release Notes

GS Series 2K version 1.8.0

This document describes the changes from GS Series 2K version 1.7.0 to version 1.8.0.

Affected products

The following products are affected:

- DWU880-GS
- DWU880A-GS
- DWU1100-GS
- DWU1100A-GS
- DWU1400-GS
- DWU1400A-GS

Purpose of release

The primary purpose of this software release is:

- Added Low Latency mode (Fast mode).
- Removed the WiFi function.
- Fixed an issue where EDID was not correctly applied when switching from HDMI 1.4 to 2.0.

Technical support

Technical support for Christie Enterprise products is available at:

- North and South America: +1-800-221-8025 or Support.Americas@christiedigital.com
- Europe, Middle East, and Africa: +44 (0) 1189 778111 or Support.EMEA@christiedigital.com
- Asia Pacific (support.apac@christiedigital.com):
 - China: +86 10 6561 0240 or tech-supportChina@christiedigital.com
 - India: +91 (80) 6708 9999 or tech-India@christiedigital.com
 - Japan: 81-3-3599-7481
 - Singapore: +65 6877-8737 or tech-Singapore@christiedigital.com
 - South Korea: +82 2 702 1601 or tech-Korea@christiedigital.com